



Production and Integration Status




Ladders installed on planes...

ON LAYER L1	ON LAYER L2	ON LAYER L3	ON LAYER L4	ON LAYER L5	ON LAYER L6	ON LAYER L7	ON LAYER L8
	L07PI002 (L ₂)		L09GI005 (L ₄)				
	L07PI004 (L ₂)		L09AI075 (L ₄) (70μm)				
	L09GI003 (L ₂)		L09AI076 (L ₄) (70μm)				
	L09GI006 (L ₂)		L09AI077 (L ₄) (70μm)				
	L09GI010 (L ₂)		L10GI015 (L ₄)				
	L09GI013 (L ₂)		L10AI079 (L ₄)				
	L10PI005 (L ₂)		L11GI017 (L ₄)				
	L10GI014 (L ₂)		L11AI081 (L ₄) (70μm)				
	L11GI004 (L ₂)		L11AI082 (L ₄) (140μm)				
	L11GI008 (L ₂)		L11AI083 (L ₄) (140μm)				
	L11GI009 (L ₂)		L12AH059 (L ₄) (70μm)				
	L11GI016 (L ₂)		L12AH060 (L ₄)				
	L12AH024 (L ₂)		L12AH061 (L ₄)				
	L12AH029 (L ₂)		L12AI015 (L ₄)				
	L12AH057 (L ₂)		L12AI048 (L ₄)				
	L12AI001 (L ₂)		L12AI083 (L ₄)				
	L12AI003 (L ₂)		L12AI084 (L ₄)				
	L12AI004 (L ₂)		L12AI085 (L ₄)				
	L12AI005 (L ₂)		L12AJ018 (L ₄)				
	L12AI006 (L ₂)		L12AJ019 (L ₄)				
	L12AJ051 (L ₂)						
	L12AJ021 (L ₂)						
	L14AI031 (L ₂)						
	L14AI042 (L ₂)						
0/30	24/24	0/22	20/20	0/20	0/22	0/24	0/30



...and ladders being manipulated

SHIELDED	READY TO BE SHIELDED	ON PHASE-2	ON REPARATION	STAND-BY
L10AI078 (L5) (70µm)	L09AI089 (L5) (140µm)	L09AI092 (L7)	L11GI001 (L5) (Hk)	L11GI007 (E) (vibr.)
L12AH030 (L7) (70µm)	L09AI090 (L5) (140µm)	L09GI012 (L5)	L12AH027 (L7) (M) (Hk)	
L12AH045 (L5) (70µm)	L09AI091 (L5) (140µm)	L12AI017 (L5)	L14AI043 (??) (K8)	
L12AI066 (L5)	L09AI102 (L7) (140µm)		L15AP098 (Hk)	
L12AI088 (L5)	L10AI080 (L5) (140µm)		L15AP110 (Hk)	
L12AJ020 (L5)	L11AI085 (L5) (140µm)		L11AI084 (L5) (Hs) (140µm)	
L12AJ022 (L5)	L12AH046 (L5) (70µm)			NEEDED FROM PG:
L12AJ023 (L7) (70µm)	L12AJ054 (??) (TB)		L12AI002 (S2.3)	
L12AJ047 (L7)	L12AJ055 (??) (TB)		L12AI009 (S7.8)	2*L07XI0XX (L7) (1 av.)
L12AJ053 (L7)	L12AJ056 (??) (TB)	L13A0025 (??) (M)	L12AI010 (Hk) (still probl.)	2*L09XI0XX (L7) (1 av.)
L14AI041 (L7)	L14AI039 (L7) (140µm)	L13A0026 (??) (M)	L12AI011 (Hs.k) (S1.8)	2*L10XI0XX (L7) (3 av.)
	L14AI040 (??) (140µm)	L13A0073 (??)	L12AI012 (Hs)	2*L11XI0XX (L5) (1 av.)
		L15AN100 (??) (diff. waf.)	L12AI013 (Hs)* (S3.7)	4*L11XI0XX (L7) (3 av.)
		L15AN101 (??)	L12AI016 (Hs.k)	2*L12XI0XX (L5) (2 av.)
L07PI003 (??) (E)	L11GI018 (??) (E)*	L15A0093 (??)	L15A0094 (S15)	5*L12XI0XX (L7) (3 av.)
L09GI002 (??) (E)		L15A0095 (??)		1*L12XJ0XX (L5) (4 av.)
L09GI011 (??) (E)		L15A0097 (??)		
L10PI001 (??) (E)		L15AP099 (??)		
L12AH028 (??) (E)		L15AP109 (??)		
L14AI032 (??) (E)				
				LEGENDA:
				E: elec. prob.
				M: metrology
				S: sensor prob.
				H: hybrid prob.
				av: available in PG
				TB: test beam
				K8: kapton misplaced
17 (11+6)	13 (12+1)	13	14	1



Mercedes Paniccia


University of Geneva



Layer L2 upside down



Installing Layer L3




Mercedes Paniccia


University of Geneva



Not enough distance between facing ladders!!!



Mercedes Paniccia



University of Geneva



What's the matter:

the distance between ladders should be enough to prevent them from touching each other (and eventually break) during vibrations which will take place at the launch, with the particular legs' fixations used for layers L3, L5 and L6 the space left is less than the minimum needed (300 μm) !

Solution:

gain flexibility gluing legs on ladders more away from Hybrids box

*First attempt: 70 μm **STILL NOT ENOUGH***


*Second attempt: 140 μm **OK***

From now on this procedure has been adopted for every ladder entering phase-2 manipulations (No effects on upper layers)

Use “old “ ladders for non problematic layers (L4 and L7)




Then layer L4 was next:





And next L5



*The four missing ladders are travelling from Perugia to Geneva...
 ..cross fingers !!!*



L5 ladders' status summary:

- *6/20 ready to be installed*
- *6/20 ready to be shielded*
- *2/20 on phase-2*
- *2/20 on reparation*
ready to be sent to Perugia for bonding
- *4/20 travelling from Perugia to Geneva*
they will enter phase-2 with high priority

Plane 3 foreseen to be completed by the end of February



Ladders' reparations:

No more bonding facility in Geneva: it has to be done in Perugia

Six ladders have been repaired and are ready to be sent to Perugia for bonding:

- ***L11GI001*** (***assigned to L5, high priority***)
- ***L11AI084*** (***assigned to L5, high priority***)
- ***L12AH027*** (***assigned to L7***)
- ***L14AI043***
- ***L15AP098***
- ***L15AP110***

One more ladder will be soon repaired:

- ***L15AO094*** (***assigned to L1, silicon sensor num. 15 to be replaced***)



Still to be repaired :

- *L12AI002 Silicon sensors num. 2 and 3 to be replaced*
- *L12AI009 Silicon sensors num. 7 and 8 to be replaced*
- *L12AI010 peculiar case*
- *L12AI011 Hybrids S and K and Silicon sensors num. 1 and 8 to be replaced*
- *L12AI012 Hybrid S to be replaced*
- *L12AI013 Hybrid S and Silicon sensors num. 3 and 7 to be replaced*
- *L12AI016 Hybrids S and K to be replaced*

Ladders needing Silicon sensors replacement will be kept in stand-by

No more S Hybrids available for replacements

We cannot go further with reparations !



What's next :

- *depending on ladders' delivering from Perugia/G&A we can proceed with layers L7 and/or L1*

What we need:

- *15/24 ladders for L7*

2 L07XIYYY

2 L09XIYYY

2 L10XIYYY

4 L11XIYYY

5 L12XIYYY

- *20/30 ladders for L1*

4 L10XOYYY

2 L11XOYYY

2 L12XOYYY

1 L13XOYYY

6 L14XOYYY

4 L15XOYYY

1 L15XNYYY

- *in the meanwhile we will have fun with the new Hybrids' production*

