



Production and Integration Status




Hybrids production status:

The first S-hybrid **2024-6-001** has been produced in Geneva




Only PCB and VAs have been bonded in order to perform an electrical test before gluing the Capacitors and then check the production method....



2024-6-001_00030.cnl



2024-6-001_00030.cnl





..the test is pretty good:

$$\langle \text{pedestal} \rangle = 362.4 \quad \text{rms} = 72.17$$

$$\langle \text{sigmas} \rangle = 1.933 \quad \text{rms} = 0.1322$$


$$\langle \text{sraw} \rangle = 6.430 \quad \text{rms} = 0.2934$$

$$\langle \text{gain} \rangle = 20.69 \quad \text{rms} = 7.077$$

That's top ten!!!



A little statistics on S-hybrids Gain :





Work is in progress:

Other three S-hybrids have been produced*:

2024-6-002

2024-6-003

2024-6-004

* VA s and Capacitors glued to PCB,
bonding will be performed in Perugia



***Ladders assembly
and
Planes Integration
Status***



Ladders installed and tested on planes

ON LAYER L1	ON LAYER L2	ON LAYER L3	ON LAYER L4	ON LAYER L5	ON LAYER L6	ON LAYER L7	ON LAYER L8
	L07P002 (L#)		L09G005 (L#)				
	L07P004 (L#)		L09A005 (L#) (70µm)				
	L09G003 (L#)		L09A006 (L#) (70µm)				
	L09G006 (L#)		L09A007 (L#) (70µm)				
	L09G010 (L#)		L10G015 (L#)				
	L09G013 (L#)		L10A009 (L#)				
	L10P005 (L#)		L11G017 (L#)				
	L10G014 (L#)		L11A081 (L#) (70µm)				
	L11G004 (L#)		L11A082 (L#) (140µm)				
	L11G008 (L#)		L11A083 (L#) (140µm)				
	L11G009 (L#)		L12A059 (L#) (70µm)				
	L11G016 (L#)		L12A060 (L#)				
	L12A034 (L#)		L12A061 (L#)				
	L12A009 (L#)		L12A015 (L#)				
	L12A007 (L#)		L12A048 (L#)				
	L12A001 (L#)		L12A083 (L#)				
	L12A003 (L#)		L12A084 (L#)				
	L12A002 (L#)		L12A085 (L#)				
	L12A005 (L#)		L12A088 (L#)				
	L12A006 (L#)		L12A089 (L#)				
	L12A051 (L#)						
	L12A071 (L#)						
	L14A031 (L#)						
	L14A042 (L#)						
0-20	24-24	0-22	20-20	0-20	0-22	0-24	0-20

LEGENDA:
 E: elec. prob.
 G: calorimetry
 S: silicon prob.
 H: hybrid prob.
 av: available in FC
 TD: test beam



Layer L4



TEST OK




Plane 3 status summary:

- *Top layer (L4) successfully tested*
- *Bottom layer (L5) :*
 - *6/20 ladders ready to be installed*
 - *13/20 ready to be shielded*
 - *1/20 still on phase-2*







Plane 3









L12AI050 at reception in Geneva (1)









L12AI050 at reception in Geneva (2)





L12AI050 at reception in Geneva (3)





A deeper look into VA 16:

STRIP	VA	VACHA	PEDESTAL	SRAW	SIGMAS	GAIN	STATUS
1000	16	40	455.45	7.71	3.09	30.38	0
1001	16	41	412.77	7.92	3.59	30.79	0
1002	16	42	401.17	7.85	3.02	30.93	0
1003	16	43	449.47	7.95	3.19	30.46	0
1004	16	44	442.23	11.8	7.95	29.83	8
1005	16	45	396.43	11.28	8.32	30.65	8
1006	16	46	402.09	8.05	3.63	30.94	0
1007	16	47	369.26	8.09	3.59	31.17	0
1008	16	48	389.65	9.35	6.22	30.83	8
1009	16	49	332.63	52.24	52.27	31.22	10
1010	16	50	389.33	77.98	72.86	26.6	10
1011	16	51	316.11	13.46	9.91	31.63	8
1012	16	52	324.04	17.48	14.14	31.34	8
1013	16	53	326.91	54.61	58.34	30.38	10
1014	16	54	393.07	135.02	141.05	20.8	26
1015	16	55	312.26	83.19	52.51	5.41	138
1016	16	56	291.87	79.16	52.57	9.42	138
1017	16	57	329.05	119.41	128.97	22.91	26
1018	16	58	259.98	46.57	45.51	32.55	10
1019	16	59	316.81	17.4	14.69	31.65	8
1020	16	60	332.47	11.18	7.08	31.37	8
1021	16	61	318.25	9.53	4.87	31.7	0
1022	16	62	286.5	8.12	3.35	32.27	0
1023	16	63	335.02	8.8	3.28	31.94	0
1024	16	64	311.23	13.79	10.78	30.41	8

VERY NOISY →
 REBONDED →
 VERY NOISY →

There is an hole of 13 channels on K-side



What happen if we take out the most noisy channel (the 54th)?

After disconnecting channel 54 the problem was still there...

Let's try to take out also the other very noisy channel (the 57th) ...

After disconnecting channel 57 the problem was still there...

And if the cause is in the two rebonded channels (55th & 56th)?

The noise did not decrease but it just spread on the neighbour channels!

Then the problem is due to the silicon.

Can we use L12AI050 as it is?

(Don't worry about L5 : L12AI049 will replace it)



VA 16 now:

STRIP	VA	VACHA	PEDESTAL	SRAW	SIGMAS	GAIN	STATUS
1000	16	40	454.75	8.61	2.77	30.4	0
1001	16	41	412.54	8.56	3.11	30.82	0
1002	16	42	402.16	8.56	2.91	31.17	0
1003	16	43	449.47	8.52	3.09	30.7	0
1004	16	44	443.66	11.33	9.76	30.17	8
1005	16	45	396.74	11.76	9.61	31.25	8
1006	16	46	403.54	8.8	3.48	30.99	0
1007	16	47	371.14	8.87	3.95	31.56	0
1008	16	48	392.46	9.07	5.43	31.03	8
1009	16	49	336.24	30.5	33.34	31.79	10
1010	16	50	386.16	42.26	51.02	29.6	10
1011	16	51	320.46	12.05	9.1	31.92	8
1012	16	52	331.01	22.97	20.67	31.8	8
1013	16	53	335.05	91.87	90.51	28.38	10
1014	16	54	397.94	5.84	6.33	25.19	8
1015	16	55	315.27	5.73	6.61	25.25	8
1016	16	56	313.34	6.15	6.83	25.34	8
1017	16	57	343.21	6.41	6.88	25.05	8
1018	16	58	268.3	79.97	77.26	32.24	10
1019	16	59	326.45	22.59	19.04	31.79	8
1020	16	60	341.07	12.63	8.76	31.44	8
1021	16	61	326.9	10.38	6.54	31.67	8
1022	16	62	293.31	8.83	3.9	32.2	0
1023	16	63	340.98	9.67	3.19	31.83	0
1024	16	64	315.37	13.04	9.96	29.88	8


DISCONNECTED

There is an hole of 14 channels on K-side !






L12AI050

l12ai050-v-g-03.cal




l12ai050-v-g-03.cal








L12AI050

l12ai050-v-g-03.cal







l12ai050-v-g-03.cal





L12AI050





There are other two cases to be discussed:

- **L12AI067**


VA 10 (S-side) have high noise
(in particular the last 25 channels).

- **L11AI088**




After phase-2 two peaks of noisy channels
have appeared in K-side (VA 14 and 16).
(L09AI089-like)



l12ai067-v-g-03.cal




l12ai067-v-g-03.cal












IL2ai067-v-g-03.cal



IL2ai067-v-g-03.cal










The L09AI089 affair:

L09AI089 at reception in Geneva...




..after Phase-2...

..after disconnecting the most noisy channel..




..a peak of 10 noisy channels appeared..

..the problem is solved!






L11AI088 at reception in Geneva...




..after Phase-2 a peak of noise, about 10 channels broad has appeared on K-side ..



..we made an accurate visual inspection to the ladder, even taking it out from the box and putting it on the jig we use to glue legs, to have access to K-side.

We did not find anything which could be related to these noisy channels, so we put the ladder back on his box and tested it again: another peak appeared on K-side!




We tried to treat the problem as we did for L09AI089..




..it has not worked!



l1Lai088-v-g-05.cal




l1Lai088-v-g-05.cal












l11ai088-v-g-05.cal



l11ai088-v-g-05.cal





15 channels 11 channels



Evolution of Integration flow will depend on:

- ***Good ladders already assembled***
 - ***How many for each type are available in Perugia?***
- ***Next Test Beam needs***
 - ***11 L09XIYYY + 6 others will be frozen until October 2004 (L3, L6 and L7 cannot be fully equipped until then)***
- ***Hybrids availability for ladders reparations***
 - ***8 S-hybrids needed to repair bad ladders located in Geneva***



...you can find this presentation and other material concerning the AMS-02 Tracker Production and Integration status on my web page:

<http://paniccia.home.cern.ch/paniccia/AMS.html>